


Chapter 14 Statistical Methods for Quality Control



Philosophies and Frameworks

- Quality
 - features and characteristics of a product or service that bears on its ability to satisfy given needs
- Total Quality
 - a people-focused management system aimed at continual increase in customer satisfaction at continually lower real cost
- Founding Fathers
 - Deming
 - advocated that managers develop a culture of commitment to quality
 - Juran
 - quality = fitness for use: quality planning, quality control, quality improvement
 - Common ground
 - management involvement
 - continuous improvement
 - importance of training
 - need to use Quality Control techniques

2

Philosophies and Frameworks

- Baldridge National Quality Award (1987)
 - created to raise awareness and to recognize US organizations
- ISO 9000 (1987)
 - international standards defining what is needed to maintain an efficient quality conformance system
 - eg: measuring system calibration, record keeping systems
- Six Sigma (late 80's)
 - Motorola's goal: quality at rate of 3.4 dpmo
 - relies heavily on statistics
 - Quality Engineering
 - consider quality when designing products and processes and identify quality problems prior to production
 - Quality Control
 - inspections/measurements to determine if quality standards are being met

3



Statistical Process Control

- Classical Hypothesis Testing generally involves making a **one-time decision based on a single sample**
- Statistical Process Control
 - many situations can change over time and must be monitored on an ongoing basis
 - why take frequent, periodic samples?

4



2 Sources of Process Variation

- Assignable Cause Variation
 - **nonrandom** influences arising out of factors that **can be corrected**
 - eg: wear & tear on machinery, operator error, contaminated materials
 - signals that the process is **out of control**
 - attempt to identify the underlying cause and take corrective action
 - how evidenced on control chart?
- Common Cause (Chance) Variation
 - **random** factors that **cannot be avoided/corrected**
 - are unavoidable even when the process is in control
 - eg: temperature changes, slight variations in materials
 - requires changing the process itself in order to reduce/eliminate
 - eg: invest in new machinery, better training, more supervision, new suppliers
- Driving analogy

5




Quality Control Inference

- H_0 : The process is in control
 - i.e., no sources of assignable cause variation are present
- H_A : The process is out of control
 - i.e., sources of assignable cause variation are present
- Type I error?
- Type II error?

6

Control Charts




- Graphically depict process performance *over time*
- Constructed after a process has stabilized and is working as it is designed to
- Used to monitor variation in an important characteristic that affects quality of the product
- Control Chart has
 - Centerline
 - Upper Control Limit
 - Lower Control Limit
 - Data points for each sampled time period
 - each time period is a hypothesis test of the process being in control
- Aids in the detection of assignable cause variation
 - how?

7

Control Charts

- Control limits are set at $CL \pm 3$ (standard errors)
 - by setting control limits at ± 3 std errors, $\alpha = \text{-----}$
 - why?



8

\bar{x} Chart : Process Mean and Standard Deviation Known

- Tracks the value of the sample mean around the process' mean when the process is in control
- Centerline set at μ

$$\text{Control limits} = \mu \pm 3\sigma_{\bar{x}}$$

9

\bar{x} Chart: Process Mean and Standard Deviation **Unknown**

- \bar{x} vs. $\bar{\bar{x}}$
- Tracks the values of the sample mean around grand mean
- Centerline set at $\bar{\bar{x}}$
- Control Limits: $UCL \& LCL = \bar{\bar{x}} \pm A_2 \bar{R}$
- Note: limits for \bar{x} chart depend on sample **ranges**
- Acme Pipe assignment

10

R-Chart

- Tracks process **variation** over time
- Higher variation suggests items tend to be dissimilar and of inconsistent quality
- Standard deviation is a more comprehensive measure, but:
 - range is easier to compute
 - range is more intuitive
 - not much information is lost when n is small (n<10)
- Centerline set at \bar{R}
- Control Limits: $UCL_R = \bar{R} D_4$ $LCL_R = \bar{R} D_3$
- Acme Pipe assignment
- Since \bar{x} chart uses the average range, an R-chart is usually constructed first; only interpret/use \bar{x} chart if R-chart indicates that process variation is in control

11

Preliminary vs Revised Control Charts

- Any initial sample falling outside the preliminary control limits should be **investigated**
- If assignable cause variation is identified, those points should be dropped and the control limits should be recalculated using the remaining samples
- Use the revised limits for monitoring the process in the future

12



Interpretation Of Control Charts

- A process is judged to be **in control** when:
 - all sample data points lie **within** UCL and LCL
 - and
 - only **random variation** is present
 - even if all sample points fall within the three sigma limits, the process may not be in control
 - nonrandom patterns or trends can indicate a change in the process and a loss of control
 - examples of nonrandom patterns:
 - something other than 68% of points within ± 1 SD of centerline
 - something other than 95% of points within ± 2 SD of centerline
 - 9 points in a row on one side of a centerline
 - 6 points in a row that are consistently increasing or decreasing

13



p Chart

- Applicable when a unit of product is judged as being either acceptable or not acceptable
- Tracks the **proportion** of defective items over time
- **p** vs. \bar{p}
- When p is unknown, pool all samples to estimate it
- Centerline set at p
- Control limits = $p \pm 3s_p = p \pm 3\sqrt{\frac{p(1-p)}{n}}$
- if LCL < 0, set it at 0 since it is impossible to have fewer than 0% defectives
- MicroChip assignment

14



Acceptance Sampling

- Sample items from a lot to infer whether the entire lot meets specifications
- Based on the number of defective items in the sample, either accept or reject the entire lot
- Advantages over 100% inspection:
 - less expensive
 - less product damage
 - fewer inspectors required
 - only option when testing is destructive
 - **inspector fatigue** (nib)

15


Acceptance Sampling

- H_0 : _____ vs H_A : _____
- Type I error
 - Reject a good-quality lot
 - Producer's risk = $P(\text{reject lot} \mid \text{good-quality lot}) = \alpha$
- Type II error
 - Accept a poor-quality lot
 - Consumer's risk = $P(\text{accept lot} \mid \text{poor-quality lot}) = \beta$
- Acceptance Criterion (c)
 - maximum number of defects allowed in sample *without* rejecting the lot
 - ensures that the AQL is maintained without rejecting more than a prescribed percentage of acceptable lots

16

Operating Characteristic Curve

- Illustrates how p , c , n affect the probability of accepting a lot




17

Selecting an Acceptance Sampling Plan

- In formulating a plan, managers specify two values for the proportion of defectives in the lot
 - Producer's Risk
 - α = the probability that a lot with p_0 defectives will be **rejected**
 - Consumer's Risk
 - β = the probability that a lot with p_1 defectives will be **accepted**
- Then, the values of n and c are selected that result in an acceptance sampling plan that comes closest to meeting both the α and β requirements specified

18



Selecting an Acceptance Sampling Plan: A Special Case

- Special case: $p_0 = p_1$
- Determine c by using Cumulative Binomial tables
 - select column for $p_0 = p_1$
 - locate c as the cumulative probability exceeding $(1 - \text{Producer's Risk})$
 - if more than c defects are found in the sample, reject the lot

$$P_B(x \leq c | n, p) \geq (1 - \text{Producer's Risk})$$

20

Multi-Stage Sampling Designs

- Rather than using a single sample to determine whether to accept a lot
- Take a preliminary sample.... then, depending on its result either: (1) accept the lot, (2) reject the lot, or (3) take another sample, pooling it with previous samples, and then decide
- Is generally **more efficient** than a single-sampling design
 - i.e., a smaller total sample size to inspect/test

21
